

## MAINTENANCE NOTE 4 (for Electronics Technicians)

Engineering Division

W/OS0321: FLP

## M003 Spares

General

1. This note describes changes and additions to spares stocked for the M003 microcomputer.
2. Effect on Other Instructions: EHB-9, Section 2.6, M003 Microcomputer System, Maintenance Note 2.

Delete the last sentence in paragraph titled "Floppy Disk Drive Assembly" on page 2.

Delete references to fixed disk drive assemblies and power supplies in paragraph titled "System Boards, Fixed Disk Drive Assemblies, and Power Supplies" on page 3.

Delete "w/mounting hardware and filler panel" in ordering description for WSN M003-1A2 on page 4.

Procedure

The number and configuration of spares stocked for the M003 microcomputer system as described in M003 Maintenance Note 2 have changed. The floppy disk drive will have no mounting hardware. The hardware is stocked separately as a kit. This enables the technician to order the drive only. The hardware kit is needed when replacing a full height drive.

The power supply is an easily replaced, modular unit. A 150-watt replacement is stocked.

Until EHB-1 is updated, use the following part numbers and descriptions when ordering.

WSN	<u>Description</u>	NSN
M003-1A2	Drive, Floppy Disk, 360K, TEAC P/N FD55B	7025-01-292-3259

EHB-9  
Issuance 91-3  
3-13-91

WSN	<u>Description</u>	NSN
MD03-1A2MP1	Kit, Mounting, Floppy Disk Drive. Contains mounting hardware and filler panel. Used with half height drive only.	6660-00-456-0000-X
MD03-1PS1	Power Supply, 150 Watt, for IBM PC-XT, JDR Microdevices P/N PS-150	6130-00-000-0060-X



J. Michael St. Clair

Chief, Engineering Division